## ON/DP/RP)ωN)381)2024 Annexure D

## **BUILDING SAFETY CERTIFICATE**

Dated: C	9/04/2024
	Dated: O

Certified that the existing building **Tapovan Vatsalyadham School**,(**English Medium**) (name of the building or premises) at **Amiyapur**, **Post- Sughad**, **Dist- Gandhinagar**. (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block	Block	Block	Block	Block	Block
	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	Ground Floor 2. CLASS Rooms	1	_	_	_	_

The building is owned/occupied by Tapovan Vatsalyadham School, (English Medium) Amiyapur, Post- Sughad, Dist- Gandhinagar. (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Panchayat Road Project Sub-Division Gondame of Department/ Govt.) on 08/04/2024 (date of inspection) in the presence of Principal Shirish P. Shah (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 08/04/2024 for a period of 03 (Three) years in accordance, with rule and subject to compliance of the specific conditions as appended.

- 1. In future, if the building has any issues relating to any cracks, collapse and leakage of water it should be reported to concerned dept and immediate action should be taken.
- 2. Should Procure Fire Safety Certificate from Fire Dept their recommendations should be followed and updated regularly.
- 3. Original Documents of the Building should be kept safety

Issued on 09/04/2024 at Gandlinagar by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name: Dy. Executive Engineer
Road Project Sub. Division

Designation: Gandhiangar

Name & Address of Department/ Office: Jilla Panduyat Sector-17, Gandle